Wednesday, 17/09/2008 2:42:05 PM

User:

Julie Lecocq

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

: 42071

Estimate Number

: 13589

P.O. Number

This Issue

: 17/09/2008 Prsht Rev. : NC

First Issue

Previous Run

Written By

Checked & Approved By

Comment

New Issue

S.O. No. :

Type

: Est. A 08/09/17

Drawing Name

Part Number

: D38231

Drawing Number

Project Number

Drawing Revision

Material

Due Date

: PROTOTYPE : KYDEX 6185 (TBD) : 03/10/2008

: REAR OVERHEAD L/H

: D38231 PROTOTYPE

Qty:

1 Um:

Each

Additional Product

Job Number:

Seq. #:

Machine Or Operation:

Description:

HAND FINISHING THERMOFORMING



Comment: HAND FINISHING THERMOFORMING

1) Machine set up

M109798.

: R&D THERMOFORMING

DL

08.09.18.

2.0

1.0

HAND FINISH TH



Comment: HAND FINISHING THERMOFORMING

1) Cut sheet to required blank size

DL 08.09.18

3.0

THERMOFORMING MACHINE



Comment: THERMOFORMING MACHINE

Thermoform as per Dwg. D3823-1and folio (FTA 9112 Prototype) using tool DT 9112

Dwg. Rev. _ Folio Rev.

Nh 08.07.18

4.0

QC2

INSPECT PARTS AS THEY COME OFF MACHINE



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

Visually inspect for proper formation of each part

DL 08.09.18

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES	WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Dart No		DAD # Foult Catagory: NC	3. Vac	No DO	\.	Dato:		

Part No:	PAR #: Fault Categoi	ry: NCR: Yes No	DQA: Date:	-
Resolution:	Disposition:	QA: N/C Closed	l: Date:	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
DATE		Description of NC	Corrective Action Section B			Verification	Approval Chief Eng	Approval QC inspector		
	STEP	Section A		Section C						
							:	}		
						1				
								1		
	1		1					1		

NOTE: Date & initial all entries

Wednesday, 17/09/2008 2:42:06 PM Date: User: Julie Lecoca **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: REAR OVERHEAD L/H Job Number: 42071 Part Number: D38231 Job Number: Seq. #: **Machine Or Operation:** Description: 5.0 QC8 SECOND CHECK Comment: SECOND CHECK 6.0 HAND FINISH TH HAND FINISHING THERMOFORMING Comment: HAND FINISHING THERMOFORMING 1) Trim to Finished Dimensions 7.0 INSPECT PARTS AS THEY COME OFF MACHINE Comment: INSPECT PARTS AS THEY COME OFF MACHINE Check dimensions to ensure conformity to drawing tolerances. 8.0 QC5 APPROVAL LUCE 06.12.6 Comment: INSPECT WORK TO CURRENT STEP 9.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: 10.0 QC21 FINAL INSPECTION/W/O RELEASE Comment: FINAL INSPECTION/W/O RELEASE Job Completion 00251A 11,08.1216

Dart Aerospace Ltd

W/O:		WO	WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHAN	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							i.	
,								
		•						
Part No	•	PAR #: Fault Categ	gory: NCF	R: Yes	No DQ	\ :	Date:	
	R	esolution: Disposition	1: QA:	N/C (Closed:		Date: _	

NCR:		•	WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC		Corrective Action Section B			A	Annanal		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector		
•										
								}		

NOTE: Date & initial all entries